


**Parts needed to mount the POR extrusion**



Extrusion (A)



End caps (B)



Mounting insert (C)



Cover (D)




LED strip (E)


**NOTE!** All LED strips must be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at [www.klusdesign.eu](http://www.klusdesign.eu)

**1.** Install the LED strip (E), insert the cover (D) and the end cap (B).



**2.** Feed the power cable and put the mounting insert (C) in the railing.



**3.** Connect power, and then mount the extrusion.

