



1. Attach the mounting bracket to the surface with bolts.

2. Bend back one side of the mounting bracket and insert the extrusion.



NOTE! Unusual dismounting of the extrusion. Move the extrusion in one of the directions in the horizontal plane, gently pull one side of the extrusion down, and remove the extrusion from the brackets.



NOTE! A list of products corresponding with the selected accessories is available at www.KlusDesign.eu