

1. FOLED-50-SUF profile (ref. C3631)

Suggested accessories:


- 2. Angular connector
- 3. Linear connector
- 4. Gland
- 5. LED tape
- 6. Cover

Table of contents



- a) Fixture assembly - p. 2
- b) Mounting the fixture to the ceiling - str. 4
- c) Installation of a stretch ceiling and cover - p. 5

NOTE! All LED tapes must be connected to a 12 V or 24 V power supply.

IMPORTANT: Not all possible mounting procedures are presented here. More mounting procedures and related accessories can be found at www.KlusDesign.eu. Drawings in these instructions are simplified and only approximate the actual shapes.







When cutting the profile at a 45-degree angle, cut it together with cover, secured with adhesive tape.






When cutting the profile at an angle of 90 degrees, the cover can be cut separately.

When joining the fixtures longitudinally, it is recommended that the cover sections did not touch where two sections of the profile are connected. This should be taken into account when cutting.








1b



Ic



To prevent the foil from tearing off, secure its hook connection with adhesive tape.



IIc

